

TAB 12

(part 2)

Nacelle Rear Module Component Serial Number List

| | Order # | PI Name | Type | Factory | RM # | MHI Serial No | Storage Location |
|----|---------|-------------|-----------|----------|------|------------------|------------------|
| 54 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | 8 | N-W 4264 | Everett Port |
| 55 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | 9 | N-W 4265 | Everett Port |
| 56 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | 10 | N-W 4266 | Everett Port |
| 57 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | 11 | N-W 4267 | Everett Port |
| 58 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | 12 | N-W 4268 | Everett Port |
| 59 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y37 | N-W 9097 | Japan |
| 60 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y38 | N-W 9098 | Japan |
| 61 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y39 | N-W 9099 | Japan |
| 62 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y48 | N-W 9108 | Japan |
| 63 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y49 | N-W 9109 | Japan |
| 64 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y50 | N-W 9110 | Japan |
| 65 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y51 | N-W 9111 | Japan |
| 66 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y52 | N-W 9112 | Japan |
| 67 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y53 | N-W 9113 | Japan |
| 68 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y54 | N-W 9114 | Japan |
| 69 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y55 | N-W 9115 | Japan |
| 70 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y56 | N-W 9116 | Japan |
| 71 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y57 | N-W 9117 | Japan |
| 72 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y58 | N-W 9118 | Japan |
| 73 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y59 | N-W 9119 | Japan |
| 74 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y60 | N-W 9120 | Japan |
| 75 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y61 | N-W 9121 | Japan |
| 76 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y62 | N-W 9122 | Japan |
| 77 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y63 | N-W 9123 | Japan |
| 78 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y64 | N-W 9124 | Japan |
| 79 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y65 | N-W 9125 | Japan |
| 80 | 0E114 | EDISON 2009 | MWT95/2.4 | Nagasaki | 16 | N-W 4044 | Galveston Port |
| 81 | 0E114 | EDISON 2009 | MWT92/2.4 | Yokohama | 47 | N-W 4075 | Galveston Port |
| 82 | 0E114 | EDISON 2009 | MWT92/2.4 | Yokohama | 49 | N-W 4077 | Galveston Port |
| 83 | 0E114 | EDISON 2009 | MWT92/2.4 | Yokohama | 50 | N-W 4078 | Galveston Port |

Nacelle Yaw Module Component Serial Number List

| | | | | | | |
|----|-------|-------------|-----------|----------|-----|-------------------------|
| | | | | | | |
| 1 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 31 | N-W 4227 Japan |
| 2 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 32 | N-W 4228 Japan |
| 3 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 33 | N-W 4229 Japan |
| 4 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 34 | N-W 4230 Japan |
| 5 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 35 | N-W 4231 Japan |
| 6 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 36 | N-W 4232 Japan |
| 7 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 37 | N-W 4233 Japan |
| 8 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 38 | N-W 4234 Japan |
| 9 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 39 | N-W 4235 Japan |
| 10 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 40 | N-W 4236 Japan |
| 11 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 41 | N-W 4237 Japan |
| 12 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 42 | N-W 4238 Japan |
| 13 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 43 | N-W 4239 Japan |
| 14 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 44 | N-W 4240 Japan |
| 15 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 45 | N-W 4241 Japan |
| 16 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 46 | N-W 4242 Japan |
| 17 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 47 | N-W 4243 Japan |
| 18 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 48 | N-W 4244 Japan |
| 19 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 49 | N-W 4245 Japan |
| 20 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 50 | N-W 4246 Japan |
| 21 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 51 | N-W 4247 Japan |
| 22 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 52 | N-W 4248 Japan |
| 23 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 53 | N-W 4249 Japan |
| 24 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 54 | N-W 4250 Japan |
| 25 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 55 | N-W 4251 Japan |
| 26 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 56 | N-W 4252 Japan |
| 27 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 57 | N-W 4253 Japan |
| 28 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 58 | N-W 4254 Japan |
| 29 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 59 | N-W 4255 Japan |
| 30 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 60 | N-W 4256 Japan |
| 31 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y13 | N-W 9073 San-Diego Port |
| 32 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y14 | N-W 9074 San-Diego Port |
| 33 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y15 | N-W 9075 San-Diego Port |
| 34 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y16 | N-W 9076 San-Diego Port |
| 35 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y17 | N-W 9077 San-Diego Port |
| 36 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y18 | N-W 9078 San-Diego Port |
| 37 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y19 | N-W 9079 San-Diego Port |
| 38 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y20 | N-W 9080 San-Diego Port |
| 39 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y21 | N-W 9081 San-Diego Port |
| 40 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y22 | N-W 9082 San-Diego Port |
| 41 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y23 | N-W 9083 San-Diego Port |
| 42 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y24 | N-W 9084 San-Diego Port |
| 43 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y25 | N-W 9085 San-Diego Port |
| 44 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y26 | N-W 9086 San-Diego Port |
| 45 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y27 | N-W 9087 San-Diego Port |
| 46 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y28 | N-W 9088 San-Diego Port |
| 47 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y29 | N-W 9089 San-Diego Port |
| 48 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y30 | N-W 9090 San-Diego Port |
| 49 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y31 | N-W 9091 San-Diego Port |
| 50 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y32 | N-W 9092 San-Diego Port |
| 51 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y33 | N-W 9093 San-Diego Port |
| 52 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y34 | N-W 9094 San-Diego Port |
| 53 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y35 | N-W 9095 San-Diego Port |
| 54 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y36 | N-W 9096 San-Diego Port |
| 55 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y37 | N-W 9097 Japan |

Nacelle Yaw Module Component Serial Number List

| 56 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y38 | N-W 9098 | Japan |
|----|-------|-------------|-----------|----------|-----|----------|-------|
| 57 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y39 | N-W 9099 | Japan |
| 58 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y40 | N-W 9100 | Japan |
| 59 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y41 | N-W 9101 | Japan |
| 60 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y42 | N-W 9102 | Japan |
| 61 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y43 | N-W 9103 | Japan |
| 62 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y44 | N-W 9104 | Japan |
| 63 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y45 | N-W 9105 | Japan |
| 64 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y46 | N-W 9106 | Japan |
| 65 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y47 | N-W 9107 | Japan |
| 66 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y48 | N-W 9108 | Japan |
| 67 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y49 | N-W 9109 | Japan |
| 68 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y50 | N-W 9110 | Japan |
| 69 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y51 | N-W 9111 | Japan |
| 70 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y52 | N-W 9112 | Japan |
| 71 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y53 | N-W 9113 | Japan |
| 72 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y54 | N-W 9114 | Japan |
| 73 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y55 | N-W 9115 | Japan |
| 74 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y56 | N-W 9116 | Japan |
| 75 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y57 | N-W 9117 | Japan |
| 76 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y58 | N-W 9118 | Japan |
| 77 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y59 | N-W 9119 | Japan |
| 78 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y60 | N-W 9120 | Japan |
| 79 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y61 | N-W 9121 | Japan |
| 80 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y62 | N-W 9122 | Japan |
| 81 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y63 | N-W 9123 | Japan |
| 82 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y64 | N-W 9124 | Japan |
| 83 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y65 | N-W 9125 | Japan |

Rotor Head Component Serial Number List

| Order # | PI Name | Type | Factory | RAI # | MHI Serial No | Storage Location | |
|---------|---------|-------------|-----------|----------|------------------|------------------|----------------|
| 1 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 31 | N-W 4227 | Japan |
| 2 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 32 | N-W 4228 | Japan |
| 3 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 33 | N-W 4229 | Japan |
| 4 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 34 | N-W 4230 | Japan |
| 5 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 35 | N-W 4231 | Japan |
| 6 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 36 | N-W 4232 | Japan |
| 7 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 37 | N-W 4233 | Japan |
| 8 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 38 | N-W 4234 | Japan |
| 9 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 39 | N-W 4235 | Japan |
| 10 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 40 | N-W 4236 | Japan |
| 11 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 41 | N-W 4237 | Japan |
| 12 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 42 | N-W 4238 | Japan |
| 13 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 43 | N-W 4239 | Japan |
| 14 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 44 | N-W 4240 | Japan |
| 15 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 45 | N-W 4241 | Japan |
| 16 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 46 | N-W 4242 | Japan |
| 17 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 47 | N-W 4243 | Japan |
| 18 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 48 | N-W 4244 | Japan |
| 19 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 49 | N-W 4245 | Japan |
| 20 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 50 | N-W 4246 | Japan |
| 21 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 51 | N-W 4247 | Japan |
| 22 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 52 | N-W 4248 | Japan |
| 23 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 53 | N-W 4249 | Japan |
| 24 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 54 | N-W 4250 | Japan |
| 25 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 55 | N-W 4251 | Japan |
| 26 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 56 | N-W 4252 | Japan |
| 27 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 57 | N-W 4253 | Japan |
| 28 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 58 | N-W 4254 | Japan |
| 29 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 59 | N-W 4255 | Japan |
| 30 | 0E208 | EDISON 2009 | MWT95/2.4 | Nagasaki | 60 | N-W 4256 | Japan |
| 31 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y13 | N-W 9073 | San-Diego Port |
| 32 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y14 | N-W 9074 | San-Diego Port |
| 33 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y15 | N-W 9075 | San-Diego Port |
| 34 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y16 | N-W 9076 | San-Diego Port |
| 35 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y17 | N-W 9077 | San-Diego Port |
| 36 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y18 | N-W 9078 | San-Diego Port |
| 37 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y19 | N-W 9079 | San-Diego Port |
| 38 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y20 | N-W 9080 | San-Diego Port |
| 39 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y21 | N-W 9081 | San-Diego Port |
| 40 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y22 | N-W 9082 | San-Diego Port |
| 41 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y23 | N-W 9083 | San-Diego Port |
| 42 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y24 | N-W 9084 | San-Diego Port |
| 43 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y25 | N-W 9085 | San-Diego Port |
| 44 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y26 | N-W 9086 | San-Diego Port |
| 45 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y27 | N-W 9087 | San-Diego Port |
| 46 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y28 | N-W 9088 | San-Diego Port |
| 47 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y29 | N-W 9089 | San-Diego Port |
| 48 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y30 | N-W 9090 | San-Diego Port |
| 49 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y31 | N-W 9091 | San-Diego Port |
| 50 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y32 | N-W 9092 | San-Diego Port |
| 51 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y33 | N-W 9093 | San-Diego Port |
| 52 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y34 | N-W 9094 | San-Diego Port |
| 53 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y35 | N-W 9095 | San-Diego Port |
| 54 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y36 | N-W 9096 | San-Diego Port |
| 55 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y37 | N-W 9097 | Japan |

Rotor Head Component Serial Number List

| Part No. | Part Name | Model | Location | Serial No. | Storage Location | | |
|----------|-----------|-------------|-----------|------------|------------------|----------|-------|
| 49 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y38 | N-W 9098 | Japan |
| 50 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y39 | N-W 9099 | Japan |
| 51 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y40 | N-W 9100 | Japan |
| 52 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y41 | N-W 9101 | Japan |
| 53 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y42 | N-W 9102 | Japan |
| 54 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y43 | N-W 9103 | Japan |
| 55 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y44 | N-W 9104 | Japan |
| 56 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y45 | N-W 9105 | Japan |
| 57 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y46 | N-W 9106 | Japan |
| 58 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y47 | N-W 9107 | Japan |
| 59 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y48 | N-W 9108 | Japan |
| 60 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y49 | N-W 9109 | Japan |
| 61 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y50 | N-W 9110 | Japan |
| 62 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y51 | N-W 9111 | Japan |
| 63 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y52 | N-W 9112 | Japan |
| 64 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y53 | N-W 9113 | Japan |
| 65 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y54 | N-W 9114 | Japan |
| 66 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y55 | N-W 9115 | Japan |
| 67 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y56 | N-W 9116 | Japan |
| 68 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y57 | N-W 9117 | Japan |
| 69 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y58 | N-W 9118 | Japan |
| 70 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y59 | N-W 9119 | Japan |
| 71 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y60 | N-W 9120 | Japan |
| 72 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y61 | N-W 9121 | Japan |
| 73 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y62 | N-W 9122 | Japan |
| 74 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y63 | N-W 9123 | Japan |
| 75 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y64 | N-W 9124 | Japan |
| 76 | 0E208 | EDISON 2009 | MWT95/2.4 | Yokohama | Y65 | N-W 9125 | Japan |

Edison 09 x 83 (Towers located in Hitchcock, Texas)

| Base | Serial # | Lower Mid | Serial # | Upper Mid | Serial # | Top | Serial # |
|------|----------|-----------|----------|-----------|----------|-----|----------|
| 1 | 1406 | 1 | 2408 | 1 | 3407 | 1 | 4406 |
| 2 | 1407 | 2 | 2406 | 2 | 3408 | 2 | 4407 |
| 3 | 1408 | 3 | 2407 | 3 | 3405 | 3 | 4405 |
| 4 | 1415 | 4 | 2410 | 4 | 3409 | 4 | 4417 |
| 5 | 1410 | 5 | 2411 | 5 | 3414 | 5 | 4415 |
| 6 | 1409 | 6 | 2414 | 6 | 3411 | 6 | 4414 |
| 7 | 1412 | 7 | 2418 | 7 | 3410 | 7 | 4412 |
| 8 | 1416 | 8 | 2416 | 8 | 3413 | 8 | 4413 |
| 9 | 1417 | 9 | 2409 | 9 | 3412 | 9 | 4416 |
| 10 | 1413 | 10 | 2405 | 10 | 3409 | 10 | 4411 |
| 11 | 1411 | 11 | 2412 | 11 | 3417 | 11 | 4410 |
| 12 | 1414 | 12 | 2417 | 12 | 3415 | 12 | 4408 |
| 13 | 1400 | 13 | 2413 | 13 | 3419 | 13 | 4409 |
| 14 | 1443 | 14 | 2444 | 14 | 3439 | 14 | 4437 |
| 15 | 1438 | 15 | 2432 | 15 | 3440 | 15 | 4436 |
| 16 | 1444 | 16 | 2436 | 16 | 3438 | 16 | 4430 |
| 17 | 1436 | 17 | 2431 | 17 | 3436 | 17 | 4442 |
| 18 | 1440 | 18 | 2430 | 18 | 3444 | 18 | 4438 |
| 19 | 1432 | 19 | 2441 | 19 | 3434 | 19 | 4443 |
| 20 | 1441 | 20 | 2438 | 20 | 3442 | 20 | 4432 |
| 21 | 1435 | 21 | 2442 | 21 | 3433 | 21 | 4433 |
| 22 | 1430 | 22 | 2437 | 22 | 3443 | 22 | 4440 |
| 23 | 1434 | 23 | 2434 | 23 | 3437 | 23 | 4431 |
| 24 | 1439 | 24 | 2433 | 24 | 3432 | 24 | 4439 |
| 25 | 1430 | 25 | 2439 | 25 | 3435 | 25 | 4444 |
| 26 | 1437 | 26 | 2440 | 26 | 3431 | 26 | 4441 |
| 27 | 1431 | 27 | 2435 | 27 | 3430 | 27 | 4434 |
| 28 | 1442 | 28 | 2443 | 28 | 3441 | 28 | 4435 |
| 29 | 1424 | 29 | 2427 | 29 | 3418 | 29 | 4427 |
| 30 | 1425 | 30 | 2418 | 30 | 3426 | 30 | 4421 |
| 31 | 1422 | 31 | 2424 | 31 | 3425 | 31 | 4419 |
| 32 | 1423 | 32 | 2420 | 32 | 3422 | 32 | 4416 |
| 33 | 1421 | 33 | 2423 | 33 | 3419 | 33 | 4423 |
| 34 | 1427 | 34 | 2421 | 34 | 3427 | 34 | 4422 |
| 35 | 1426 | 35 | 2422 | 35 | 3423 | 35 | 4420 |
| 36 | 1420 | 36 | 2419 | 36 | 3424 | 36 | 4425 |
| 37 | 1418 | 37 | 2428 | 37 | 3421 | 37 | 4426 |
| 38 | 1410 | 38 | 2429 | 38 | 3429 | 38 | 4424 |
| 39 | 1428 | 39 | 2451 | 39 | 3455 | 39 | 4483 |
| 40 | 1451 | 40 | 2447 | 40 | 3452 | 40 | 4485 |
| 41 | 1448 | 41 | 2445 | 41 | 3455 | 41 | 4429 |
| 42 | 1449 | 42 | 2448 | 42 | 3463 | 42 | 4449 |
| 43 | 1454 | 43 | 2481 | 43 | 3449 | 43 | 4451 |
| 44 | 1455 | 44 | 2459 | 44 | 3451 | 44 | 4448 |
| 45 | 1453 | 45 | 2462 | 45 | 3453 | 45 | 4442 |
| 46 | 1454 | 46 | 2455 | 46 | 3462 | 46 | 4445 |
| 47 | 1452 | 47 | 2483 | 47 | 3454 | 47 | 4464 |

| | |
|----|------|
| 48 | 1462 |
| 49 | 1453 |
| 50 | 1461 |
| 51 | 1456 |
| 52 | 1460 |
| 53 | 1460 |
| 54 | 1429 |
| 55 | 1458 |
| 56 | 1459 |
| 57 | 1457 |
| 58 | 1447 |
| 59 | 1446 |
| 60 | 1450 |
| 61 | 1448 |
| 62 | 1475 |
| 63 | 1473 |
| 64 | 1468 |
| 65 | 1472 |
| 66 | 1477 |
| 67 | 1486 |
| 68 | 1483 |
| 69 | 1471 |
| 70 | 1467 |
| 71 | 1470 |
| 72 | 1474 |
| 73 | 1476 |
| 74 | 1479 |
| 75 | 1483 |
| 76 | 1486 |
| 77 | 1482 |
| 78 | 1487 |
| 79 | 1491 |
| 80 | 1495 |
| 81 | 1478 |
| 82 | 1480 |
| 83 | 1484 |

| | |
|----|------|
| 48 | 2464 |
| 49 | 2465 |
| 50 | 2480 |
| 51 | 2450 |
| 52 | 2451 |
| 53 | 2445 |
| 54 | 2452 |
| 55 | 2446 |
| 56 | 2454 |
| 57 | 2458 |
| 58 | 2453 |
| 59 | 2429 |
| 60 | 2429 |
| 61 | 2458 |
| 62 | 2480 |
| 63 | 2466 |
| 64 | 2468 |
| 65 | 2473 |
| 66 | 2467 |
| 67 | 2472 |
| 68 | 2476 |
| 69 | 2475 |
| 70 | 2471 |
| 71 | 2474 |
| 72 | 2477 |
| 73 | 2470 |
| 74 | 2480 |
| 75 | 2479 |
| 76 | 2481 |
| 77 | 2478 |
| 78 | 2483 |
| 79 | 2482 |
| 80 | 2487 |
| 81 | 2484 |
| 82 | 2485 |
| 83 | 2486 |

| | |
|----|------|
| 48 | 3484 |
| 49 | 3445 |
| 50 | 3456 |
| 51 | 3448 |
| 52 | 3428 |
| 53 | 3429 |
| 54 | 3460 |
| 55 | 3460 |
| 56 | 3448 |
| 57 | 3447 |
| 58 | 3457 |
| 59 | 3459 |
| 60 | 3461 |
| 61 | 3455 |
| 62 | 3477 |
| 63 | 3472 |
| 64 | 3474 |
| 65 | 3466 |
| 66 | 3469 |
| 67 | 3473 |
| 68 | 3470 |
| 69 | 3487 |
| 70 | 3466 |
| 71 | 3471 |
| 72 | 3475 |
| 73 | 3476 |
| 74 | 3478 |
| 75 | 3465 |
| 76 | 3485 |
| 77 | 3487 |
| 78 | 3484 |
| 79 | 3483 |
| 80 | 3481 |
| 81 | 3479 |
| 82 | 3482 |
| 83 | 3480 |

| | |
|----|------|
| 48 | 4428 |
| 49 | 4450 |
| 50 | 4480 |
| 51 | 4459 |
| 52 | 4458 |
| 53 | 4456 |
| 54 | 4462 |
| 55 | 4481 |
| 56 | 4457 |
| 57 | 4454 |
| 58 | 4456 |
| 59 | 4447 |
| 60 | 4453 |
| 61 | 4452 |
| 62 | 4477 |
| 63 | 4486 |
| 64 | 4467 |
| 65 | 4469 |
| 66 | 4474 |
| 67 | 4476 |
| 68 | 4473 |
| 69 | 4475 |
| 70 | 4471 |
| 71 | 4472 |
| 72 | 4468 |
| 73 | 4470 |
| 74 | 4480 |
| 75 | 4484 |
| 76 | 4481 |
| 77 | 4479 |
| 78 | 4482 |
| 79 | 4485 |
| 80 | 4487 |
| 81 | 4478 |
| 82 | 4486 |
| 83 | 4483 |

Edison 09 x 83 (Blades located in
Santa Teresa, New Mexico)

| SET # | Blade Pos | Blade # | Moment Class | Moment |
|-------|--------------|---------|-----------------|--------|
| 1 | POS.2 | 46-1089 | E | 175443 |
| | POS.1 | 46-1085 | E | 175894 |
| | POS.3 | 46-1081 | E | 175586 |
| 2 | POS.3 | 46-1100 | G | 176844 |
| | POS.1 | 46-1099 | G | 177104 |
| | POS.2 | 46-1071 | G | 176830 |
| 3 | POS.2 | 46-1061 | E | 176315 |
| | POS.3 | 46-1073 | E | 175401 |
| | POS.1 | 46-1083 | E | 175485 |
| 4 | POS.3 | 46-1092 | E | 175869 |
| | POS.1 | 46-1098 | E | 175896 |
| | POS.2 | 46-1101 | E | 175597 |
| 5 | POS.3 | 46-1102 | A | 172895 |
| | POS.1 | 46-1140 | A | 173006 |
| | POS.2 | 46-1137 | Z | 171651 |
| 6 | POS.3 | 46-1116 | B | 173259 |
| | POS.1 | 46-1112 | B | 173523 |
| | POS.2 | 46-1074 | B | 173057 |
| 7 | POS.3 | 46-1072 | F | 176444 |
| | POS.1 | 46-1103 | F | 176525 |
| | POS.2 | 46-1067 | F | 176141 |
| 8 | POS.3 | 46-1086 | E | 175856 |
| | POS.2 | 46-1088 | E | 175481 |
| | POS.1 | 46-1094 | E | 175982 |
| 9 | POS.2 | 46-1091 | D | 174614 |
| | POS.3 | 46-1077 | D | 174718 |
| | POS.1 | 46-1079 | D | 175206 |
| 10 | POS.1 | 46-1090 | C | 174504 |
| | POS.2 | 46-1105 | C | 173917 |
| | POS.3 | 46-1084 | C | 174191 |
| 11 | POS.1 | 46-1087 | F | 176338 |
| | POS.2 | 46-1064 | F | 176084 |
| | POS.3 | 46-1070 | F | 176318 |
| 12 | POS.3 | 46-1078 | D | 174687 |
| | POS.2 | 46-1132 | D | 174648 |
| | POS.1 | 46-1096 | D | 174751 |
| 13 | POS.2 | 46-1082 | E | 176464 |
| | POS.1 | 46-1120 | G | 176916 |
| | POS.3 | 46-1093 | F | 176558 |

| | | | | |
|----|-------|---------|---|--------|
| 14 | POS.1 | 46-1080 | C | 174421 |
| | POS.2 | 46-1133 | C | 174148 |
| | POS.3 | 46-1160 | C | 174314 |
| 15 | POS.2 | 46-1104 | B | 173259 |
| | POS.3 | 46-1125 | B | 173360 |
| | POS.1 | 46-1128 | B | 173505 |
| 16 | POS.1 | 46-1121 | D | 175161 |
| | POS.3 | 46-1138 | D | 174979 |
| | POS.2 | 46-0968 | D | 174624 |
| 17 | POS.1 | 46-1124 | E | 175803 |
| | POS.2 | 46-1097 | E | 175313 |
| | POS.3 | 46-1122 | E | 175782 |
| 18 | POS.2 | 46-1147 | B | 173755 |
| | POS.1 | 46-1068 | C | 174491 |
| | POS.3 | 46-1136 | C | 174144 |
| 19 | POS.2 | 46-1115 | C | 173915 |
| | POS.3 | 46-1076 | C | 173966 |
| | POS.1 | 46-1109 | C | 174270 |
| 20 | POS.3 | 46-1134 | B | 173587 |
| | POS.2 | 46-1042 | B | 173055 |
| | POS.1 | 46-1095 | B | 173754 |
| 21 | POS.3 | 46-1113 | D | 175048 |
| | POS.1 | 46-1118 | D | 175176 |
| | POS.2 | 46-1114 | D | 174832 |
| 22 | POS.2 | 46-1146 | C | 174169 |
| | POS.1 | 46-1107 | C | 174416 |
| | POS.3 | 46-1123 | C | 174209 |
| 23 | POS.3 | 46-1144 | D | 174775 |
| | POS.2 | 46-1169 | D | 174599 |
| | POS.1 | 46-1135 | D | 175117 |
| 24 | POS.2 | 46-1110 | C | 173852 |
| | POS.3 | 46-1129 | C | 174068 |
| | POS.1 | 46-1117 | C | 174247 |
| 25 | POS.1 | 46-1065 | D | 175269 |
| | POS.2 | 46-1163 | D | 174694 |
| | POS.3 | 46-1130 | D | 174928 |
| 26 | POS.1 | 46-1154 | F | 176788 |
| | POS.3 | 46-1131 | F | 176168 |
| | POS.2 | 46-1142 | E | 175838 |
| 27 | POS.3 | 46-1119 | E | 175829 |
| | POS.2 | 46-1127 | E | 175522 |
| | POS.1 | 46-1157 | E | 175884 |
| 28 | POS.2 | 46-1145 | C | 174510 |
| | POS.3 | 46-1149 | D | 174635 |

| | | | | |
|----|-------|---------|---|--------|
| | POS.1 | 46-1152 | D | 174901 |
| 29 | POS.2 | 46-1158 | D | 174828 |
| | POS.3 | 46-1164 | D | 174723 |
| | POS.1 | 46-1148 | E | 175559 |
| 30 | POS.3 | 46-1151 | D | 174788 |
| | POS.1 | 46-1155 | D | 175174 |
| | POS.2 | 46-1075 | D | 174762 |
| 31 | POS.3 | 46-1150 | D | 174731 |
| | POS.2 | 46-1167 | D | 174576 |
| | POS.1 | 46-1159 | D | 174769 |
| 32 | POS.1 | 46-1161 | E | 175813 |
| | POS.2 | 46-1156 | E | 175351 |
| | POS.3 | 46-1170 | E | 175788 |
| 33 | POS.2 | 46-1176 | D | 174781 |
| | POS.3 | 46-1171 | D | 174886 |
| | POS.1 | 46-1143 | D | 175016 |
| 34 | POS.2 | 46-1162 | E | 175440 |
| | POS.3 | 46-1153 | E | 175546 |
| | POS.1 | 46-1185 | E | 175870 |
| 35 | POS.2 | 46-1184 | E | 175325 |
| | POS.3 | 46-1177 | F | 176362 |
| | POS.1 | 46-1189 | F | 176440 |
| 36 | POS.3 | 46-1180 | D | 174763 |
| | POS.1 | 46-1178 | D | 175012 |
| | POS.2 | 46-1111 | D | 174643 |
| 37 | POS.2 | 46-1175 | B | 173508 |
| | POS.1 | 46-1172 | C | 174232 |
| | POS.3 | 46-1174 | C | 174186 |
| 38 | POS.2 | 46-1173 | B | 173131 |
| | POS.3 | 46-1192 | B | 173536 |
| | POS.1 | 46-1168 | B | 173742 |
| 39 | POS.3 | 46-1179 | D | 175091 |
| | POS.1 | 46-1207 | E | 175978 |
| | POS.2 | 46-1106 | D | 174718 |
| 40 | POS.2 | 46-1195 | B | 173699 |
| | POS.1 | 46-1208 | C | 174402 |
| | POS.3 | 46-1181 | C | 174340 |
| 41 | POS.3 | 46-1186 | E | 175464 |
| | POS.1 | 46-1182 | E | 175566 |
| | POS.2 | 46-1183 | E | 175407 |
| 42 | POS.3 | 46-1204 | D | 175097 |
| | POS.2 | 46-1187 | D | 174794 |
| | POS.1 | 46-1198 | D | 175181 |
| 43 | POS.3 | 46-1190 | D | 174876 |

| | | | | |
|----|-------|---------|---|--------|
| | POS.2 | 46-1193 | D | 174731 |
| | POS.1 | 46-1201 | D | 175161 |
| 44 | POS.3 | 46-1223 | D | 175141 |
| | POS.1 | 46-1214 | D | 175297 |
| | POS.2 | 46-1191 | D | 174632 |
| 45 | POS.1 | 46-1212 | C | 174442 |
| | POS.2 | 46-1217 | C | 174180 |
| | POS.3 | 46-1196 | C | 174428 |
| 46 | POS.2 | 46-1210 | E | 175407 |
| | POS.3 | 46-1205 | E | 175639 |
| | POS.1 | 46-1213 | E | 175977 |
| 47 | POS.3 | 46-1188 | E | 175635 |
| | POS.2 | 46-1216 | E | 175623 |
| | POS.1 | 46-1194 | F | 176131 |
| 48 | POS.3 | 46-1211 | G | 177003 |
| | POS.1 | 46-1228 | G | 177115 |
| | POS.2 | 46-1241 | G | 176824 |
| 49 | POS.2 | 46-1202 | E | 175357 |
| | POS.3 | 46-1215 | E | 175883 |
| | POS.1 | 46-1232 | F | 176761 |
| 50 | POS.2 | 46-1209 | F | 176412 |
| | POS.3 | 46-1222 | F | 176440 |
| | POS.1 | 46-1225 | F | 176711 |
| 51 | POS.3 | 46-1197 | D | 174964 |
| | POS.1 | 46-1203 | D | 174965 |
| | POS.2 | 46-1238 | D | 174630 |
| 52 | POS.3 | 46-1200 | F | 176058 |
| | POS.2 | 46-1199 | E | 175919 |
| | POS.1 | 46-1218 | G | 177116 |
| 53 | POS.1 | 46-1250 | E | 175999 |
| | POS.3 | 46-1219 | E | 175889 |
| | POS.2 | 46-1233 | E | 175566 |
| 54 | POS.2 | 46-1239 | F | 176153 |
| | POS.3 | 46-1251 | F | 176552 |
| | POS.1 | 46-1230 | F | 176723 |
| 55 | POS.3 | 46-1226 | F | 176446 |
| | POS.2 | 46-1245 | F | 176242 |
| | POS.1 | 46-1240 | F | 176526 |
| 56 | POS.3 | 46-1234 | D | 174850 |
| | POS.1 | 46-1242 | D | 175186 |
| | POS.2 | 46-1221 | C | 173978 |
| 57 | POS.2 | 46-1236 | D | 175230 |
| | POS.3 | 46-1220 | E | 175610 |
| | POS.1 | 46-1229 | F | 176697 |

| | | | | |
|----|-------|---------|---|--------|
| 58 | POS.3 | 46-1235 | G | 177378 |
| | POS.1 | 46-1263 | H | 178164 |
| | POS.2 | 46-1243 | G | 177300 |
| 59 | POS.3 | 46-1227 | E | 175762 |
| | POS.1 | 46-1246 | E | 175974 |
| | POS.2 | 46-1248 | F | 175307 |
| 60 | POS.1 | 46-1224 | E | 176033 |
| | POS.2 | 46-1237 | D | 175122 |
| | POS.3 | 46-1247 | E | 175742 |
| 61 | POS.2 | 46-1252 | E | 175427 |
| | POS.1 | 46-1231 | F | 176502 |
| | POS.3 | 46-1244 | E | 175546 |
| 62 | POS.3 | 46-1249 | F | 176168 |
| | POS.2 | 46-1260 | F | 176110 |
| | POS.1 | 46-1269 | G | 177242 |
| 63 | POS.2 | 46-1264 | E | 175622 |
| | POS.1 | 46-1271 | F | 176413 |
| | POS.3 | 46-1254 | E | 175982 |
| 64 | POS.1 | 46-1266 | F | 176059 |
| | POS.3 | 46-1267 | E | 175533 |
| | POS.2 | 46-1272 | D | 175065 |
| 65 | POS.3 | 46-1253 | D | 175288 |
| | POS.2 | 46-1270 | C | 174442 |
| | POS.1 | 46-1274 | F | 175782 |
| 66 | POS.2 | 46-1300 | G | 176908 |
| | POS.1 | 46-1265 | F | 178126 |
| | POS.3 | 46-1268 | G | 177236 |
| 67 | POS.1 | 46-1262 | F | 176754 |
| | POS.2 | 46-1279 | E | 176009 |
| | POS.3 | 46-1257 | F | 176590 |
| 68 | POS.2 | 46-1256 | C | 174522 |
| | POS.3 | 46-1280 | D | 174730 |
| | POS.1 | 46-1261 | D | 175149 |
| 69 | POS.1 | 46-1258 | E | 176079 |
| | POS.2 | 46-1287 | D | 175255 |
| | POS.3 | 46-1275 | E | 175930 |
| 70 | POS.1 | 46-1273 | D | 175142 |
| | POS.2 | 46-1278 | G | 174162 |
| | POS.3 | 46-1281 | D | 174902 |
| 71 | POS.1 | 46-1277 | G | 177091 |
| | POS.2 | 46-1284 | F | 176362 |
| | POS.3 | 46-1313 | F | 176621 |
| 72 | POS.1 | 46-1290 | E | 176166 |
| | POS.3 | 46-1255 | E | 175895 |


| | | | | |
|----|-------|---------|---|--------|
| 73 | POS 2 | 46-1283 | D | 175262 |
| | POS 2 | 46-1292 | C | 173998 |
| | POS 3 | 46-1299 | D | 174978 |
| | POS 1 | 46-1295 | E | 175376 |
| 74 | POS 2 | 46-1293 | E | 175669 |
| | POS 3 | 46-1289 | F | 178356 |
| | POS 1 | 46-1286 | F | 176679 |
| 75 | POS 2 | 46-1206 | E | 175768 |
| | POS 3 | 46-1297 | F | 176078 |
| | POS 1 | 46-1291 | F | 176350 |
| 76 | POS 1 | 46-1294 | E | 175946 |
| | POS 3 | 46-1304 | E | 175483 |
| | POS 2 | 46-1305 | E | 175325 |
| 77 | POS 1 | 46-1139 | F | 176497 |
| | POS 3 | 46-1296 | F | 176211 |
| | POS 2 | 46-1308 | F | 176052 |
| 78 | POS 2 | 46-1285 | D | 174674 |
| | POS 3 | 46-1307 | D | 175047 |
| | POS 1 | 46-1302 | D | 175288 |
| 79 | POS 1 | 46-1316 | E | 175895 |
| | POS 3 | 46-1311 | E | 175647 |
| | POS 2 | 46-1309 | D | 174914 |
| 80 | POS 3 | 46-1259 | H | 178108 |
| | POS 1 | 46-1298 | I | 178624 |
| | POS 2 | 46-1288 | G | 177007 |
| 81 | POS 2 | 46-1317 | E | 175997 |
| | POS 1 | 46-1301 | F | 176330 |
| | POS 3 | 46-1314 | F | 178103 |
| 82 | POS 3 | 46-1315 | G | 177254 |
| | POS 2 | 46-1306 | G | 176869 |
| | POS 1 | 46-1331 | G | 177469 |
| 83 | POS 1 | 46-1310 | D | 175042 |
| | POS 3 | 46-1303 | D | 174978 |
| | POS 2 | 46-1328 | C | 174276 |

EXHIBIT B

TALOGA WORK PLAN

LA1 - 146259.02

44-111 3



See Exhibit A and Exhibit B for additional information and incorporated exhibits.

31

Seller's Obligations:

1. Seller shall be ready to hand over the WTG components for Owner's loading and delivery at least at the rate of one set per Business Day in accordance with the schedule above.

For the avoidance of doubt, loading of such stored WTG components shall be the responsibility of Owner; provided, however, that Seller shall make available to Owner, or its contractor (at no cost to Owner or its contractor), any Special Tools at the Storage Locations and/or necessary rigging to facilitate the loading of the WTG components. At Santa Teresa, Seller shall provide Owner with the use of the blade cradles necessary for the shipment of the blades to the Project Site and shall all necessary loading support work and equipment to load, including cranes for loading, at the rate and cost to be paid by Owner to Seller of \$800/blade (US\$2,400/WTG), which rate assumes a return time for such blade cradles as set forth above. So long as Owner and/or its contractors are utilizing such property (blade cradles, etc.) of Seller, Owner and/or its contractors shall maintain insurance reasonably acceptable to Seller and name Seller as an additional insured to cover the risk of loss which shall be with Owner for all such Seller property during such utilization.

2. Seller shall provide Owner with at least two (2) pre-commissioning crews capable of performing the required pre-commissioning activities for the period commencing on January 17, 2011 and Owner shall pay the Commissioning Fees for all such personnel on an as rendered basis as set forth in Section 5.2.10 of the Agreement.

3. Seller shall provide Owner with at least three (3) commissioning crews capable of performing the required Commissioning activities for the period commencing on March 14, 2011 and Owner shall pay Commissioning Fees for all such personnel on an as rendered basis as set forth in Section 5.2.10 of the Agreement.

4. Seller shall provide Owner with not less than four (4) Technical Advisors to support the activities set forth above for the period commencing on December 1, 2010 and Owner shall pay Technical Advisory Fees for all such personnel on an as rendered basis as set forth in Section 5.2.9 of the Agreement.

Owner's Obligations:

1. Owner shall pay Commissioning Fees and Technical Advisory Fees on an as rendered basis and in accordance with Sections 5.2.9 and 5.2.10 of the Agreement and otherwise in accordance with the schedule and manpower assumptions provided herein (unless such schedule or manpower assumptions are modified on three (3) weeks advance written notice by Owner). The method and amount of payment to be determined in accordance with Sections 5.2.9 and 5.2.10 of the Agreement. For the avoidance of doubt, if Owner gives less than three (3) weeks prior written notice of a schedule change or manpower reduction, then Owner shall remain obligated to pay the Commissioning Fees and/or Technical Advisory Fees per the original schedule or manpower assumptions for the balance of such three (3) week period) (excluding travel and other per diems not actually incurred).

B-2

2. On not less than three (3) weeks prior advance written notice, Owner shall be entitled to (i) adjust the manpower assumptions or (ii) delay the Site mobilization schedule of some or all of such personnel. On three (3) weeks prior advance written notice, Owner may request an acceleration of the scheduling assumptions and Seller shall endeavor to accommodate such request but shall not be obligated to do so.

3. Pre-Commissioning Equipment. Owner shall provide the one (1) each of the following items of equipment to Seller for each pre-commissioning crew: (a) 3-Phase 240V 200KVA diesel generator including its fuel/maintenance and transport vehicle between each WTG, (b) 240V to 690 V transformer and (c) cabling from diesel generator to transformer to ground cabinet.

4. Maintenance for non commissioned units. If any WTG is not Commissioned for a period in excess of thirty (30) days from its Mechanical Completion, the following maintenance shall be executed by Seller at Owner's cost. In no event shall such time for such maintenance performed by Seller be counted for the Commissioning periods for the purpose of LD calculation, as applicable.

[Once per thirty (30) day period]

- a. Lubrication of gearbox/main shaft
- b. Check of yaw brake pressure
- c. Check of blade pitch angle (accumulator gas pressure on each pitch cylinder)

[Every ninety (90) days]

- a. Greasing the generator bearing
- b. Checking brush wearing for the rotor/generator
- c. Uneven lubrication of blade bearings
- d. Unexpected oil and grease leakage check
- e. Lightning damage
- f. Discharging the UPS batteries

B-3

EXHIBIT C

PINNACLE PAYMENT SCHEDULE

LA1 - 146259.02

Exhibit C
Pinnacle Wind Turbines
Project Specific Payment Schedule

| Milestone | Amount Paid |
|---|-------------------------------------|
| Effective Date of Settlement | \$59,610,056.54 US Dollars |
| | 931,733,100 JY |
| Delivery to Site (as set forth in Section 5.2.16 of the Master Supply Agreement) | \$3,146,882 |
| Commissioning (as set forth in Section 5.2.17 of the Master Supply Agreement) | \$3,501,797 less 200% of Punch List |

EXHIBIT E

FORM OF DISMISSAL

LA1 - 146259.02

1 GIBSON, DUNN & CRUTCHER LLP
2 ROBERT E. PALMER (SBN116892), RPalmer@gibsondunn.com
3 DAVID A. SEGAL (SBN166635), DSegal@gibsondunn.com
4 KELLY A. ROOSEVELT (SBN222969), KARoosevelt@gibsondunn.com
5 JENNIFER M. MACAULEY (SBN261127), JMacaulay@gibsondunn.com
3161 Michelson Drive
Irvine, California 92612-4412
Telephone: 949.451.3800
Facsimile: 949.451.4220

6 Attorneys for Plaintiff
7 EDISON MISSION ENERGY

8 SUPERIOR COURT OF THE STATE OF CALIFORNIA
9 FOR THE COUNTY OF ORANGE
10 CIVIL COMPLEX CENTER
11

12 EDISON MISSION ENERGY, a Delaware
13 Corporation,

14 Plaintiff,

15 MITSUBISHI POWER SYSTEMS AMERICAS,
16 INC., a Delaware Corporation, MITSUBISHI
17 HEAVY INDUSTRIES, LTD., a Japan
Corporation, and DOES 1-10,

18 Defendants.
19

20 AND RELATED CROSS-ACTION
21
22
23
24
25
26
27
28

CASE NO. 30-2010-00355044

JUDGE: THIERRY PATRICK COLAW
DEPARTMENT: CX104

STIPULATION AND [PROPOSED] ORDER
DISMISSING ACTION

Action Filed: March 19, 2010
Second Amended Complaint filed: August 9, 2010
Cross-Complaint filed: September 9, 2010
Trial Date: Not Yet Assigned

Gibson, Dunn &
Crutcher LLP

STIPULATION AND [PROPOSED] ORDER DISMISSING ACTION

1 Plaintiff and Cross-Defendant, Edison Mission Energy, and Defendants and Cross-
 2 Complainants Mitsubishi Power Systems Americas, Inc. and Mitsubishi Heavy Industries, Ltd.,
 3 hereby stipulate and agree as follows.

4 WHEREAS, following extensive arms-length negotiations, and for valuable consideration, the
 5 parties entered into a written Settlement and Mutual Release Agreement effective as of October __,
 6 2010 (the "Settlement") to resolve all claims and cross-claims in the above-captioned action.

7 WHEREAS, pursuant to the Settlement, the parties agreed that: (1) all claims and cross-
 8 claims in the action shall be dismissed with prejudice; (2) the parties shall each bear their own
 9 attorneys' fees and costs associated with this action; and (3) the Court shall retain jurisdiction
 10 pursuant to California Code of Civil Procedure Section 664.6 to enforce the terms of the parties'
 11 Settlement.

12 NOW, THEREFORE, IT IS HEREBY STIPULATED AND AGREED, by and between the
 13 parties, that:

- 14 1. All claims and cross-claims in the action shall be dismissed with prejudice;
- 15 2. The parties shall each bear their own attorneys' fees and costs associated with this
 16 action; and
- 17 3. The Court shall retain jurisdiction pursuant to California Code of Civil Procedure
 18 Section 664.6 to enforce the terms of the parties' Settlement.

19 **IT IS SO STIPULATED AND AGREED:**

20 Dated: _____ **GIBSON, DUNN & CRUTCHER LLP**

21 By: _____
 22 Robert E. Palmer
 23 Attorney for Edison Mission Energy

24 Dated: _____ **HOLLAND & KNIGHT LLP**

25 By: _____
 26 Ben W. Subin
 27 Attorneys for Mitsubishi Power Systems
 28 Americas, Inc. and Mitsubishi Heavy
 Industries, Ltd.

ORDER

Pursuant to the stipulation of the parties, and the terms of the Settlement and Mutual Release between the parties effective October __, 2010, IT IS HEREBY ORDERED, ADJUDGED, AND DECREED that:

1. The Clerk of the Court shall enter a final judgment dismissing this action with prejudice;

2. Each party shall bear their own attorneys' fees and costs associated with this action;

3. Except as otherwise provided in the Settlement, upon the Effective Date thereof, the parties shall be deemed to have fully, finally, and forever released, relinquished and discharged all released claims;

4. Neither the Settlement, nor any act performed or document executed pursuant to or in furtherance of the Settlement: (i) is or may be deemed to be or may be used as an admission of, or evidence of, the validity or lack thereof of any released claim, or of any wrongdoing or liability of any party; or (ii) is or may be deemed to be or may be used as an admission of, or evidence of, any fault or omission of any of party in any civil, criminal, or administrative proceeding in any court, administrative agency, or other tribunal; and

5. Without affecting the finality of the final judgment in this action in any way, this Court hereby retains continuing jurisdiction over: (a) implementation of this Settlement; and (b) all parties hereto for the purpose of construing, enforcing, and administering the Settlement pursuant to California Code of Civil Procedure Section 664.6.

IT IS SO ORDERED.

DATED: _____, 2010

HONORABLE THIERRY PATRICK COLAW
JUDGE OF THE SUPERIOR COURT

100939702_1.DOC

CERTIFICATE OF SERVICE

I, Marisela Arvayo, declare as follows:

I am employed in the County of Orange, State of California; I am over the age of eighteen years and am not a party to this action; my business address is 3161 Michelson Drive, Irvine, California 92612-4412, in said County and State. On October _____, 2010, I served the following document(s):

STIPULATION AND [PROPOSED] ORDER DISMISSING ACTION

on the parties stated below, by placing a true copy thereof in an envelope addressed as shown below by the following means of service:

**Attorneys for Defendants
Mitsubishi Power Systems
Americas, Inc. and
Mitsubishi Heavy
Industries, LTD.**

Paul C. Workman, Esq.
Laura Coombe, Esq.
HOLLAND & KNIGHT LLP
633 West Fifth Street, 21st Floor
Los Angeles, CA 90071-2040

Phone: (213) 896-2400
Facsimile: (213) 896-2450
Email: paul.workman@hklaw.com
laura.coombe@hklaw.com

-and-

Ben W. Subin, Esq.
William B. Wilson, Esq.
Monte S. Starr, Esq.
HOLLAND & KNIGHT LLP
200 South Orange Avenue, Suite 2600
Orlando, FL 32801

Phone: (407) 425-8500
Facsimile: (407) 244-5288
Email: ben.subin@hklaw.com
bill.wilson@hklaw.com
monte.starr@hklaw.com

- ☐ **BY MAIL:** I placed a true copy in a sealed envelope addressed as indicated above, on the above-mentioned date. I am familiar with the firm's practice of collection and processing correspondence for mailing. It is deposited with the U.S. Postal Service on that same day in the ordinary course of business. I am aware that on motion of party served, service is presumed invalid if postal cancellation date or postage meter date is more than one day after date of deposit for mailing in affidavit.
- ☐ **BY PERSONAL SERVICE:** I placed a true copy in a sealed envelope addressed to each person[s] named at the address(es) shown and giving same to a messenger for personal delivery before 5:00 p.m. on the above-mentioned date.
- ☐ **BY FAX:** From fax number (949) 451-4220, I caused each such document to be transmitted by fax machine, to the parties and numbers indicated above, under California Rules of Court, Rule 2.306. The fax machine that I used complied with Rule 2.301 and no error was reported by the machine.
- ☐ **BY UPS NEXT DAY AIR:** On the above-mentioned date, I placed a true copy of the above mentioned document(s), together with an unsigned copy of this declaration, in a sealed envelope or package designated by the United Parcel Service with delivery fees paid or provided for, addressed to the person(s) as indicated above and deposited same in a box or other facility regularly maintained by United Parcel Service or delivered same to an authorized courier or driver authorized by United Parcel Service to receive documents.

☒ I am employed in the office of Robert E. Palmer, a member of the bar of this court, and that the foregoing document(s) was(were) printed on recycled paper.

☒ (STATE) I declare under penalty of perjury under the laws of the State of California that the foregoing is true and correct.

Executed on October _____, 2010.

Marisela Arvayo

Gibson, Dunn &
Crouter LLP

STIPULATION AND ORDER FOR PROTECTIVE ORDER

EXHIBIT L

LABOR RATE ESCALATION PROVISIONS

LA1 - 146259.02



Los Angeles Office • 100 Bayview Circle, Suite 4000 • Newport Beach CA 92660 • Phone 949-856-8445 • Fax 949-856-4481/4482

Exhibit L

Technical Advisor Fee Schedule

Rate Schedule (Standard Rate)

| | |
|---------------------------------------|---------------|
| Site Manager Class: | \$153.00/Hour |
| Mechanical Engineer: | \$142.00/Hour |
| Electrical Engineer: | \$142.00/Hour |
| Commissioning Engineer (Mechanical.): | \$142.00/Hour |
| Commissioning Engineer (Electrical.): | \$142.00/Hour |

A. APPLICATIONS

- | | | |
|----|--|-------------------------|
| 1. | Travel Day | 8 hours Standard Rate |
| 2. | Weekdays up to 8 Hours/day between 7:00am & 6:00pm | Standard Rate |
| 3. | Time in excess of 8 Hours/day (Service/Standby at weekdays) | 1.5 Times Standard Rate |
| 4. | Saturday Service | 1.5 Times Standard Rate |
| 5. | Service time of Sundays, Holiday or time in excess of 8 hrs/day at Saturday, & nocturnal time between 10:00pm & 6:00a.m. | 2.0 Times Standard Rate |
| 6. | Standby Time from Monday to Friday except holidays. | Standard Rate |

Note 1: Tax: Any tax related to Technical Advisory Fee, Owner shall pay to Seller in the manner specified in Section 5.1.5 of the Supply Agreement

Note 2: All subcontracted specialists will be billed to Owner at cost plus 15% administration.

Note 3: Standby Time means any non-working hours from Monday to Friday except holidays in case working hours of a certain day does not reach eight (8) hours.

B. EXPENSES

1. Travel Expenses such as Airfare (Business class for International flights), Taxi, Rental car, etc. are invoiced at cost plus 10% handling fee.
2. Lodging is invoiced at cost plus 10% handling fee.
3. A per diem of \$70.00/day is charged to cover food and incidentals.
4. Telephone, telefax, and telex communications shall be invoiced at cost.
5. Expenses (Passport, Visa, etc.) in connection with technical advisor's preparation for departure will be charged at cost plus 10% handling fee.

C. TERMS

1. Validity:

These rates are valid until the first anniversary of NTP date and are subject to escalation once a year pursuant to the provisions set forth below.

2. Payment:

100% cash payment within 30 days after presentation of Seller's invoice

3. Time Sheet:

The Seller's technical advisor will submit the time sheet weekly to Owner's representative at the Site who shall approve time sheets weekly. If Owner has any questions per time sheets, Owner shall assess and clarify with Seller's representative at the Site and determine the approved time sheet within a week.

If Owner fails to make the approved time sheet within a week, the Seller is entitled to claim the Technical Advisory Fee based on the time sheet which the Seller has submitted to Owner.

Technical Advisor Fee Schedule

Technical Advisor Fee stipulated in Exhibit L of Supply Agreement and Service Labor Rate in Exhibit D-1 of Maintenance and Service Agreement shall be increased annually based on the increase, if any, in the GDPIPD from the NTP Date to each anniversary thereafter, and such increase shall apply through the following year. First adjustment shall occur on the first anniversary of the NTP Date. In no event shall such fee and rate be adjusted downward.